



July 2019 –Vancouver BC

**1986 Rolls-Royce Silver Spur #\_GCX14703**  
**New Price: \$19,900**

*"If you have not driven a Rolls-Royce before, the Silver Spur will prove a total revelation."*

A well-preserved and maintained example of the peak of 1980's luxury - offered for sale at \$19,900.

**GENERAL:**

Long Wheelbase version of the Silver Spirit. One of only 6240 hand-made from 1980-1989. Delivered to Newport Beach, California. **Properly imported** to Canada in May, 2015 at 40,200 miles. Today at 46,500 (average 1370 miles/year from new).

Currently on Collector's plates.

Maintained mostly by Octagon Motors in Vancouver. Receipts included in sale.

Always garaged - Comes with indoor and outdoor covers.

Carfax available (to 2015).

**EXTERIOR:**

Very good exterior with minor imperfections. Paint is the original Dark Oyster. Chrome in excellent condition.

**INTERIOR:**

The interior leather is in very good shape with no tears or other issues. Carpets are original with custom carpet mats to protect them. Original owner's manuals included. Service Manual on DVD. Windows all work well with recent service on the motors at Octagon.

Practical upgrade to a Pioneer flip-up audio unit provides a back-up camera, Bluetooth, CD audio, DVD video, as well as hands-free phone capabilities. Central locking and an immobilizer professionally installed at the same time. Original Rolls Royce audio system is included in sale and could be re-installed.

Air conditioning blows ice cold.

Dash and center panel wood refinished at Madera Concepts in Santa Barbara, California. They are known for their concours quality work.

#### **MECHANICAL:**

Braking system (a common area of concern) is thoroughly sorted with new OEM accumulators. Work was done at Octagon. New rear brake pads were installed at that time. A set of new pads (from Flying Spares, UK) comes with the car but are not yet required.

Hydro-pneumatic suspension and self-leveling works as it should.

Some engine mounts replaced

Tires all in good condition.

#### **Imperfections:**

- Cruise control not currently working - no troubleshooting has been performed.
- Seat motor controls can be erratic. Fortunately, this model does not have 'memory seat controls' so no expensive modules involved.
- Engine compartment light non-functioning.
- Headlight washer bottle has a leak; however, the windscreen washer bottle and systems work just fine (and wipers are near new).
- The lock mechanism on glove box needs to be adjusted.

Serious enquiries only.

Contact Martin @ [1986.rr.silver.spur@gmail.com](mailto:1986.rr.silver.spur@gmail.com)

Photo album at: <https://photos.app.goo.gl/egSRQTu2ZYjTFu2L9>